

PLOT NO 445, SECTOR 3, NAVI MUMBAI MAHARASHTRA

REJECTION DETAIL

Name	No.	Party	TC	TR	Rej %	Rej.Val	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	Prod.Val
LT SWITCHGEAR 25A X 12 PC	-	LARSEN TOUBRO	1000	6	0.60	26		1	1	1	1	1	1														4400
			1000	6		26	0.00	1.00	1.00	1.00	1.00	1.00	1.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	4400

Overall Rejection %
0.600 %
 Overall Rejection Value
Rs. 26.400

Total Checked **1000**
 Total Rejection **6**
 P.P.M **6000.0000**

- Defect Categories**
- 1) WRINKLES
 - 2) PATCHES
 - 3) DELAMINATION
 - 4) UNEVEN COATING
 - 5) COATING SPOT
 - 6) UNCURED COATING
 - 7) OUT PUNCHING
 - 8) CRACKING
 - 9) EMBOSSING/LEAFING
 - 10) SCRATCHES
 - 11) EXTRA GLUE
 - 12) GLUE MISS
 - 13) OVER LAPING
 - 14) CROSS PASTING
 - 15) SCUM
 - 16) WATER MARKS
 - 17) REGISTER OUT
 - 18) COLOR VARIATION
 - 19) OUT PRINTING
 - 20) OTHER